ControLinks Replacement | CLR

ControLinks by Honeywell is obsolete and they offer no support for it at all. We have an out-of-the-box solution called ControLinks Replacement AKA CLR

If the customer has a ControLinks system that they would like to replace, you will have to know how many actuators they have to properly quote a new CLR system.

Question 1:
- How many actuators are currently on your existing Controlinks system?
  - ○ Their options are 2, 3, or 4 actuators. This is to determine which version of the CLR they will require

Question 2:
- Do you have room in your existing panel for the retrofit CLR?
  - ○ Needed space: 21"W x 16-15/16"H x 6-3/4"D for back panel to mount inside their cabinet.
  - ○ 13-3/4"W x 12-1/4"H on the panel door to mount HMI.

Question 3:
- What is the model number of your existing flame safeguard?
  - ○ We will have crossover wiring diagrams for the most common FSG, RM7800, Burnerlogix etc.
    - § If they have an older obsolete flame safeguard, we will need to add additional time to create that diagram.

Note- You will still quote without this (crossover) information

Make sure to:

Get images of the system they have along with the brackets and/or mounting of their actuators.
   We have brackets but they are not a "one size fits all" thing so, we will need to knw this before hand.